















220-240V~ 50/60Hz




3 x 1.5mm ²	3 x 2.5mm ²
$\varnothing = 3 \times 1.5\text{mm}^2$ $I_{\text{max}} = 8.5\text{A}$ $V = 250\text{V}$	$\varnothing = 3 \times 2.5\text{mm}^2$ $I_{\text{max}} = 8.5\text{A}$ $V = 250\text{V}$



5 x 1.5mm ²	5 x 2.5mm ²
$\varnothing = 5 \times 1.5\text{mm}^2$ $I_{\text{max}} = 8.5\text{A}$ $V = 250\text{V}$	$\varnothing = 5 \times 2.5\text{mm}^2$ $I_{\text{max}} = 8.5\text{A}$ $V = 250\text{V}$



3a ?
3 x 2.5mm² / 5 x 2.5mm²



3b ?
5 x 1.5mm² / 3 x 1.5mm²

