


# Cable ladder – Z4


Test result for a salt spray test according to SS-EN ISO 61537



The chart shows the number of hours per class and our Z4 results.



After 768 h red rust has occurred.  
HDG cable ladders fails after 1000 h.



After 1000 h white rust has occurred  
on the Z4 cable ladders, it does not  
affect function or service life.